

# Oil Field Environmental Incident Summary

**Incident:** 20151025134527      **Date/Time of Notice:** 10/25/2015 13:45

**Responsible Party:** Firetail Energy Services Inc

**Well Operator:** WHITING OIL AND GAS CORPORATION

**Well Name:** CHARGING EAGLE 10-14-11-2H3

**Field Name:** TWIN BUTTES

**Well File #:** 25293

**Date Incident:** 10/24/2015      **Time Incident:** 10 am

**Facility ID Number:**

**County:** DUNN

**Twp:** 147

**Rng:** 92

**Sec:** 14

**Qtr:** SE NW

**Location Description:**

**Submitted By:** Michael Koele

**Received By:**

**Contact Person:** Terry Fredericks  
7956 7th stNW  
Halliday, nd 58636

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:** 0.5 Mile

**Type of Incident:** Other

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	3	Barrels	0.5	Barrels	3	barrels
Other						

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 1/8/2016

**Clean Up Concluded:** 10/30/2015

**Risk Evaluation:**

TBD

**Areal Extent:**

10 \* 25 ft was on facility pad in front of tanks just outside of berm.

**Potential Environmental Impacts:**

TBD

**Action Taken or Planned:**

Sent out vac truck cleaned up surface water. rest will have to be cleaned after one call. Driver had 2 day off no pay and will go threw more training to in sure when he closes valves he closes all of them and shuts pump down before walking away.

**Wastes Disposal Location:** Approved Disposal

**Agencies Involved:** BIA, TAT, MHA

**Updates**

---

**Date:** 10/27/2015 **Status:** Reviewed - Assigned to Other Agency

**Author:** Souder, Taylor

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release remained on location according to the report. NDIC retains oversight.